M20:

.RAW files can convertsin to others .BMP format with this tool.

.RAW converts .BMP :

Width: 4608, Height: 3456

IN RAW: 12bits,

OUT RAW: 12bits.

Color Gain : please fill the value what you like, if you wanna to gain a picture like the file of.jpg, You can open the picture .jpg by Notebook, then you will get a specific value. (You will get two photo files after one time capturing.)

Press `RAW --> BMP`

Then, you can get .BMP file.

After that, then we can try to edit the.bmp through Photo Shop

SJ5000x:

.RAW converts into different .BMP format（like: 8bits,16bits,12bits）:

Width: 4000, Height: 3000

IN RAW: 12bits

OUT RAW: 12 bits

Color Gain : please fill the value what you like, if you wanna to gain a picture like the file of.jpg, You can open the picture .jpg by Notebook, then you will get a specific value. (You will get two photo files after one time capturing.)

Press `RAW --> BMP` ,

Then, you will get a different .BMP format file.

After that, then we can try to edit the.bmp through Photo Shop

Open Raw File

Filename

2016_0520_185751_001.RAW

Add   Remove All

Width 4608

Height 3456

CFA

In RAW
- ○ 8 bits
- ○ 16 bits
- ● 12 bits
- ○ 10 bits

Out RAW
- ○ 8 bits
- ○ 16 bits
- ● 12 bits

Color Gain (R, G, B)

438   256   501

Gamma

Load   Reset

RAW --> BMP   RAW --> RAW

Splite RAW